

IMC Potash, Esterhazy Column Repairs

STRUCTURE: Thickener Area Structural Column Bases

LOCATION: K-2 Minesite, Esterhazy

PROJECT DATE: 2 Phases – 2002 & 2003

JOB DURATION: 3 weeks / Phase

CLIENT CONTACT: Terry Heal

AREA: 32 Column Bases Repaired

CONTRACTOR: Vector Construction Ltd.
Saskatchewan Branch



PROJECT DESCRIPTION:

Problem: Flooding of the area with salt brine causing surface deterioration of the concrete and corrosion of the reinforcing steel.

Repair System: - repair to original dimension with Target Redi-Crete
- Gemite Cem-Kote Flex ST surface coating

Procedure:

- i) Proper surface preparation and repair reinforcing steel as required.
- ii) Form to original dimension and pour with Target Redi-Crete.
- iii) Spray apply Gemite Cem-Kote Flex ST as per manufacturer's recommended procedures.



CORPORATE OFFICE

474 Dovercourt Drive
Winnipeg, Manitoba, R3Y 1G4
Ph. (204) 489-6300
Fax (204) 489-6033
Email: vector@vectorgroup.com

REGIONAL OFFICES

Manitoba Winnipeg (204) 489-6300
Ontario (North) Thunder Bay (807) 346-4405
Ontario (South) Stoney Creek (905) 662-4020
Saskatchewan Saskatoon (306) 934-3533
Alberta Spruce Grove (780) 962-6778

North Dakota Fargo (701) 280-9697
Nebraska Sioux City (402) 494-9305
Iowa Cedar Rapids (319) 364-5355

#33-03SK_IMC